

### Digiprog 3 Eeprom & Direkt Programmierung

Epprom Lesen / Schreiben

24C01 24C02 24C04 24C08 24C16 24C32 24C64 24C128 24C256  
24C512 24C44

35080 / 080D0WQ / 160D0WQ

93C06 93C06\_8 93CS46 93C46 93C46\_8 93C65 93CS56 93C56\_8  
93CS66 93C66 93C66\_8 93C76 93C76\_8 93CCS86 93C86 93C86\_8

S95010 S95020 S95040 S95080 S95160 S95320 S95640 S95128  
S95256 S95512 S95P01 S95P02 S95P04 S95P08

MCU

NEC 780828 780973 780973-8 68HC08 68HC912 MOT 9s12 4k MOT  
9S12x 4K

Alfa	145 - 146 ST 147 - 93C86 / NEC78 156 - HC11 159 - 93C86 / ECU 95080 / EDC16 95640 166 - HC11 / 93C56 Brera - 93C86 / ECU 95080 Mito - 24C16
Aston Martin	DB7 DB9 Vanquish Vantage
Audi	A3 (8L) 93C56 / M73 HC12 / Repair 999999 A4 (8D) VDO - 1997 93C46 / 93C56 V1 & V2 / UKNSI A4 (8E) Bosch 24C0X / M73 A4 (8H) Bosch 24C0X / M73 A4 (8K) 95320 A5 (8T) 95320 A6 (4A) 93C46 A6 (4B) 93C56 / M73 HC12 / A7 (4G) 95320 A8 (4D) VDO 93C56 / 24C16 A8 (4E) 93C86 / Flash C / DXXX A8 (4H) 95320 TT (8N) HC12 / Repair 999999 TT (8J) 24C32 Q5 (8R) 95320 Q7 (4L) 95320

Bentley Continental	24C08 / 24C16
BMW	<p>***Für CAS3 HCS12 wird R270 / CAS4 &amp; EWS 4 das R290 benötigt***</p> <p>1 er (E8X / F20) Tacho 35080</p> <p>3 er (E36) 1991 - 2004 / 93Cs46 / 93Cs56 (E46) Tacho 35080 / CS66 / LCM / EWS3 (E90) Tacho 35080 / CAS (F30) Tacho 160D0WQ / FEM Can Filter benutzen</p> <p>5 er (E34) 1989 - 1996 (E39) SW13 I7 CS66 / 35080 / EWS3 / LCM V1-3 (E60) Tacho 35080 / CAS (F07/F10/F11 ) Tacho 35080</p> <p>6 er (E63/E64) Tacho 35080 / CAS3 (F13) Tacho 35080</p> <p>7 er (E32) 1989 - 1993 (E38) SW13 I7 CS66 / 35080 / EWS3 / LCM V1-3 (E65/E66) Tacho 35080 / CAS (F01/F02/F03) Tacho 35080</p> <p>X1 (E84) Tacho 35080 / X3 (E83) Tacho 35080 / EWS3 X5 (E53/E70) Tacho 35080 / EWS3 / CAS3 X6 (E71) Tacho 35080 / EWS3 / CAS3 Z3 93Cs46 / 93Cs56 Z4 (E85) Tacho 35080 / LCM / EWS3 Z8 (E52) Tacho 35080 / LCM / EWS3</p>
Brilliance	BS4 / BS6 Eeprom 24C01
Cadillac	<p>CTS 93C66 Deville 93C56 Escalade 95020 Seville 93C46 &amp; HC11 CTS 93C66</p>
Chevrolet	<p>Alero - S95P02 Avalanche - S95P02 Blazer - S95P02 Escalade - S95P02 HHR - S95P02 Tahoe - S95P02 Trailblazer - S95P02</p> <p>Aveo - 93C56 / HC05</p> <p>Camaro, Cruze - BSI 24C16 &amp; 25160</p> <p>Captiva Epica, Lecetti - Eeprom 93Cs46</p> <p>KALOS - HC05 / 93C56 Malibu - NEC78 MATIZ</p>

	Nubira - 93C46 Spark - 93C86 Tahoe
Chrysler	300C - HC12 300M - HC11, HC12 Neon - HC11 Pacifica - HC12, HCS12 PT Cruiser - HC11, HC12, 93C76 Sebring - HC12 Voyager - HC12
Citroen	***BSI (Auto): S95128, 24C128, S95160, S95080, NEC78  Berlingo - Tacho 9502 / HC08 C1 - Tacho 93Cs56 C2 - Tacho 95020, 93C46, 93C56, 93C66 - BSI (Auto) C3 - Tacho 95020, 93C46, 93C56, 93C66 - BSI (Auto) C4 - Tacho 95020, 93C46, 93C56, 93C66 - BSI (Auto) C4 Picasso - Tacho 93C66 - BSI (Auto) C5 - Tacho HC08, 93C76 / BSI HC12 - BSI (Auto) C6 - Tacho 93C66 - BSI (Auto) C8 - Tacho 1L & 2M - 95020 / BSI HC12 - BSI (Auto) C Crosser - Tacho 93C86 DS3 - Tacho 93C66 - BSI (Auto) DS4 - Tacho 24C16 - BSI (Auto) Evasion - Jaeger Tacho Jumper - Tacho 950X0 Jumpy - Tacho 95020 - BSI (Auto) Nemo - Tacho S95040, S95080, S95160, S95320 Relay - Tacho S95040, S95080, S95160, S95320 Saxo Xantia Sagem Tacho 93C46 Xsara - Tacho 93C46, NEC78, CS66 - BSI 95040, NEC78 Xsara Picasso - Tacho C55 / BSI NEC78
Corvette	Tacho S95P02 & 93C76
Dacia	Duster Logan Sandero - Tacho 93C56
Daihatsu	Sirion 93C46, 93C56, 93C66 Terios 93C56
Dodge	Avenger - HCS12 Caliber - HCS12 Caravan - HCS12 Challenger - HC12 Charger - HC12 Durange - 93C46, HCS12 Journey - 93C86 Magnum - HC12 Nitro - 93C76 RAM - HCS12, 24C16
Fiat	500 - 950X0 & ECU MJD 95320 Bravo - 93C56, HC08, ST624X

	Daily - 93C56, 95oXo Doblo - 950x0, ECU 95640 Ducato - 95XX0, ECU 95640 & 95P08 Fiorino - 950X0 & ECU MJD 95320 Idea - 950X0 Marea - HC08, HC11 Multipla - ab 2002 bis 2006 -Eeprom 93C56 Panda - 950X0 Panda - Jaeger HC08, 95XX0 Scudo - HC08, HC05, 25020 - BSI 95128 Sedici - 93CS66 Seicento - S95040, S95080, S95160, S95320 Stilo - HC12, HCS12 Ulysse - HC05, 95020 - BSI HC12,  BSI (Auto): S95128, 24C128, S95160, S95080, NEC78
Ferrari	California - 95080 360 Modena - 24C02 550M - 24C02 F50 Stradale - 24C16 430 Scuderia - 24C16 Enzo - 24C02 612 Scaglietti - 24C16 599 GTB/GTO - 24C16 458 Italia - 95320
Ford	Bantam - 24C16 C-MAX - HCS12, 95320 Connct - HC12, HCS12 Cougar - HC11 E450 Escape - HC11, HCS12 Explorer - HC12, HCS12 93C86 F150 - HC11, HCS12, 24C16 F250 - HC12 F350 - HC12 F450 - HCS12 Fiesta - HC11, 24C08, Nec78, HCS12 Falcon - 24C16 Focus - 24c16, HCS12, 95320 Fusion - 24C08, HCS12 GT 24C08 KA - NEC78. 95080 Kuga - HCS12, 24C32 Maverick - HC11, HCS12 Mondeo - HC12, HCS12, 24C16 Mustang - HC11, HCS12, 24C16 Ranger - 93C56, 24C16 Scorpio SMax - HCS12, 24C16 Territory - 93C56

	Thunderbird - HC12 Transit - 93C66, 24C16, 93C76, 95320 VAN150 - 93Cs46 Windstar - HC11
GMC	Savana - S95P02
Holden	Commodore VX
Honda	Accord - 93C56, 93C66, 93C86 Civic - 93C56, 93C76 CR-V - 93C56, 93C66, 93C76, HC12 CR-Z - 93C76 FRV - 93C66 HRV - 93C46 JAZZ - 93C56, 93C66, 93C86 Legend - 93C46, 93C66 Logo - 93C46 Shuttle - 93C46 S2000 - 93C56, 93C66 Stream - 93C56
Hummer	H2 - AT212, 95P08, 95080 H3 - 93C56 - BOX S95040
Hyundai	Accent - 93C56 Coupe - 93C46 Elantra - NEC78 Getz - 93C46, 24C08 H1 - 93C66 I10 - 24C08 I20 - 24C16 I30 - 93C56, 93C66 IX35 - 93C66 IX55 - 93C56 Matrix 93C46 Santa Fe - 93C46, NEC78 Sontana - NEC78, 93C56 Terracan - NEC78, 93C56 Tucson - 93C46 XG30 - 93C46
Infiniti	93Cs46 FX45 - CS66 QX56 - HCS12
Isuzu	D-Max - 93CS66 Panther - 93CS66 Rodeo - 93C56 Trooper - 93Cs46
Jaguar	S-Type - K11, HC12, HCS12 XF - 24C64 Xj - 11/DU, 11/DU 91-93, 11/DU 95, HC12, 24C16 XK - HC11, 24C64 X-Type

Jeep	Cherokee - 93C56, HC08, 93C76, 24C16 Commander - 93C76 Compass - 93C76 Grand Cherokee - HC05, HC12, 93C76, 93C86 Patriot - 93C76 Wrangler - 93C56, HC11, HC12, 93C76,
KIA	Carens - 93Cs46 Carnival - 93Cs46 Ceed - 93Cs46 Carato - 93Cs46 Mentor - 93Cs46 Rio - 93Cs46 Picanto - 93C46, 93C56 Sorento - 93C46, 24C16 Sportage - 93C56, 24C16
Lamborghini	Aventador - 24C16 Gallardo - 24C08 Murcielago - X2444, 93C86
Lancia	Lybra - HC11 Thema - 24C16 Thesis - 93C56 Zeta - Jaeger Phedra - 95020 & BSI: HC12, BSI (Auto): S95128, 24C128, S95160, S95080, NEC78 Y - 93C66
Ladrover	Freelander - 93C46, HC12, 35080, 93C76 / BCU S95320  Range Rover - Tacho 24C16, 28C16, 35080, 93C86, LCM, EWS  Defender - VDO 93C46 Discovery - Tacho 93Cs56, 35080, 24C16 / BSI Evoque - 93C76
LDV	Convoy Van - 93Cs46
Lexus	LS 200 - 93C46 IS 200 - 93C56 LS300 - 93C46 LS 400 - 93C46 LS 430 - 93C46 RX 300 - 93C46 GS 450H - 93C46 L460 RA57 - 93C56
Lincoln	Aviator Mark LT Navigator - HC11, HCS12 Towncar - HC11, HCS12
Lotus	Elise - HC11 Elise - 24C04 Exige S
Mahindra	Scorpio 93C46

Maserati	Quattroporte - 950X0 Gran Turismo - S95040, S95160, S95320
Mazda	2 - 93C56, 93C66 3 - 93C56 323 - 93C46, 93C56 5 - 93C56 6 - 93C56, 93C66 626 - 93C56 BT50 - 93C56 CX5 - 93C76 CX7 - 93CS66 MPV - 93Cs46 MX5 - 93C46, 93C56 Premacy - 93Cs56 RX8 - 93C56 Tribute - HC11 Xedos 9 - 93C46
Mercedes	C- Klasse -9.1995 - VDO C- Klasse - Motometer C- Klasse - 9.1995 - 3.1998 Sprinter - Kienzle Diag / VDO Diag Sprinter - Kinzle 24C02, 24C04 / VDO 93CS46 Sprinter - MJ2000 Tacho 93C66 / Fahrtenschreiber 24C02  Sprinter - Tacho 25640 / EZS HCS12 ( Wird R270 benötigt )  G Klasse Box S-KL -6.1996  ML (W166) - 95640 GL (X164) - 24C16 A-Klasse (W169) - 24C04, 24C016, 24C08, 24C32 A-Klasse (W176) - 95640 CLA-Klasse (W117) - 95640 B-Klasse (W245) - 24C04, 24C016, 24C08, 24C32 B-Klasse (W246) - 95640 S-Klasse (W220) - 93C66, 24C04, HC08 C-Klasse (W203) - 93C86, 24C16, HC08 / EZS HCS12 (Wird R270 benötigt) C-Klasse (W204) - 24C128, 95128 GLK-Klasse (X204) - 24C128, 95128 E-Klasse (A207) - 24C128, 95128 E-Klasse (C207) - 24C128, 95128 CLK-Klasse (W209) - 24C16 / EZS HCS12 (Wird R270 benötigt) E-Klasse (W211) - 24C16, 24C32, ZGW / EZS HCS12 (Wird R270 benötigt) E-Klasse (W212) - 24C128, 25128 CL-Klasse (W216) - 24C08



	CLS-Klasse (W219) - 24C16,24C31 / EZS HCS12 (Wird R270 benötigt) CLS-Klasse (W218) - 95128, 24C128 R-Klasse (W251) - 24C16 / EZS HCS12 (Wird R270 benötigt) G-Klasse (W493) - 24C16 / EZS HCS12 (Wird R270 benötigt) SLK-Klasse (R171) - 24C16 / EZS HCS12 (Wird R270 benötigt ) SLK-Klasse (R172) - 95640 / EZS HCS12 (Wird R270 benötigt ) SLS-Klasse (R197) - 24C128 SL-Klasse (R230) - 93C86, 24C16,HC08 / EZS HCS12 (Wird R270 benötigt) SL-Klasse (R231) - 95640 Veano Viano Vito - 25640, HC08 / EZS HCS12 (Wird R270 benötigt)
Mercury	Mariner - HC11, HCS12
Mini Cooper	-2003 Tacho / BOX - HC12
	2003-2006 Tacho / Navi HC12 - Box 93C76
	2007-???? Tacho 35080 / CAS R270
Mitsubishi	Canter - 93CS46 Carisma - 93CS46 Colt - 93CS46, 93CS56, 93CS66 Eclipse - 93CS46, 93CS56 Galant - 93CS46 Grandis - 93CS46 Lancer - 93CS56, 93Cs86 L200 - 93CS46, 93CS56 Outlander - 93CS56, 93CS86 V1 & V2 Pajero - 93CS46, 93CS56, 93CS66 Pinin - 93CS46 Shogun - 93CS56 Spacegear - 93CS46 Spacerunner - 93CS46 Spacestar - 93CS46 Spacewagon - 93CS46
Nissan	Almera - 93CS46, 93CS56, 93CS66 Armana - HCS12 Cabstar - 93CS66 GTR - 93CS76 Interstar - 93CS66 Juke - 93CS86 Maxima - 93CS46, 93CS56 Micra - 93CS46, 93CS66 Murano - 93CS66 Navara - 93CS56, 93CS56, HCS12 Note - 93CS66 Pathfinder - 93CS46, 93CS56, HCS12 & HCS12X Patrol - 93CS56, 93CS66



	Pick Up - 93CS56, 93CS56 Primastar - 93CS66 Primera - Diag, 93CS46, 93CS56, 93CS66 Qashqai - 93CS66, HCS12 Terano - HC08, 93CS66 Tino - 93CS56 Titan - HCS12 X-Trail - 93CS56, 93CS66 Serena - 93CS56 Skyline - 93CS56, 93CS66 350Z - 93CS66 370Z - 93CS86
Opel	Agila - NEC78 Antara - 93C86 / ECU 95640 Astra - 93C56, 24C02, 35080 / BSI 25160, 24C16 ECU Bosch 95160, 95640 / MJD 95320 Corsa - 35080 Frontera - 93CS46 GT - BOX S95080 Insignia - BSI 24C16, 25160 Meriva - ECU MJD 95320 Mokka - BSI 24C16, 25160 Monaro - 24C02 Monterey - 93CS46 Movano - 93C67, 93C66, NEC78 Signum - 93CS66, ECU 95160 Speedster - 24C06, HC11 Vectra - 93CS46, 93CS66 / ECU 95160 Vivaro - 95020, 93C66, 93C76 Zafira - 35080, 24C02 / ECU 95160, 95640
Peugeot	106 - Diag 107 - 93C56 206 - Jaeger 206 - Tacho: S95020 / BSI (Auto) 207 - Tacho 93C66 / BSI (Auto) 306 - Diag 307 - Tacho 95020, NEC78 / BSI HC12 + BSI (Auto) 308 - Tacho 95020 / BSI (Auto) 3008 - Tacho 95080 / BSI (Auto) 406 - Sagem 93CS46 / Jaeger / VDO 407 - Tacho 93C66 / BSI (Auto) 4007 - 93C86 508 - Tacho 95080 / BSI 95256 607 - VDO 806 - Jaeger 807 - Tacho 95020 / BSI HC12 + BSI (Auto) Boxer - Tacho 950X0 Expert - Tacho 95020 / BSI (Auto) E7 - Tacho 95020 / BSI (Auto) Partner - Tacho S95020 / BSI NEC78 - BSI (Auto)

	RCZ - Tacho 95040 / BSI (Auto)  ***BSI (Auto): S95128, 24C128, S95160, S95080, NEC78
Pontiac	Trans Am 99 - S95P02 Trans Sport - HC12 Solstice - S95P02
Porsche	928 - 93CS46 Boxter (986) - 93C56, 93C86 Boxter (987) - 93C86 / MCU- BOX 9508, 95320, 95128 Cayenne (I) - 24C08 Cayenne (II) - 95640 Cayman (987) - 93C86 / MCU- BOX 9508, 95320, 95128 911 (996) - Tacho 93C56, 93C86 / MCU- BOX 9508, 95320, 95128 911 (997) - Tacho 93C56, 93C86 / MCU- BOX 9508, 95320, 95128 Panamera - 95640 / MCU- BOX 9508, 95320, 95128
Renault	Avantime - Diag Clio - Sagem 93CS46, MotoMeter HC08, NEC78, 93C56, 24C04  Espace - 93C56, 93C66, HC08 / BSI HC08 Kangoo - 93C46, 93C66, 93C76 Koleos - 24C16 Laguna (-2008) - 93C46, HC08, HC12, HCS12 Laguna (2008-) - Tacho 24C16 / ABS 95160 Master - 93C56 / TVI 93C66, 93C76 Megane (-2008) - 93C46, HC08, HC12, HCS12 Megane (2008-) - Tacho 24C16 / ABS 95160 Modus - 93C56, 93C66 Safrane - 93C46, 93C56 Scenic - HC08, 24C16 / ABS 95160 Trafic - NEC, 93C66 Twingo - Borg, VDO, 93C66 Vel Satis - HC12 Wind - 93C76
Rover / MG	Rover 75 - 93CS56 MGF - 93CS46 25/45 - 93C46
SAAB	AAB 900 - 93C46 SAAB 95 - 93C46 SAAB 93 - 93CS56, 24C02, HCS12 SAAB 9-7 - S95P02
Seat	Alhambra - 93C86 Arosa - TRW 24C0X Cordoba - TRW 24C0X, HCS12 Exeo - Bosch Crypte 24C0X Ibiza (6k/6L) - TRW 24C0X, HCS12 Inca - TRW 24C0X Leon (1M) - Bosch 24C0X

	MII - MM7 HCS12 Toledo (1L) - VDO 3.5-3.9 - 93CS46 / TRW Toledo (1M) - BOSCH 24C0X Toledo (5P) - 24CXX
Skoda	Citigo - MM7 HCS12 Fabia - 24C0X, HCS12 Octavia - 24C0X Roomster - HCS12
Smart	93C66, 93C86, 93CS66 Smart Box  Smart Forfour - Tacho, Box Smart Fortwo - Tacho, Box
SSANG YONG	Kyron - 93C56 Rexton - HC12, 93C46 Rodius - 93C46
STILL	R70 - 24C04
Subaru	Forester - 93CS46, 93CS56, 93CS76 Impreza - 93CS56, 93CS76 Justy - 93CS56 Legacy - 93CS56, 93CS76 Outback - 93CS56 Tribeca - 93CS66
Suzuki	Alto - 93CS46, 93CS66 Grand Vitara - 24C16 Ignis - 93CS46, 93CS56 Jimny - 93CS46, 93CS56 Kizashi - 24C16 Liana - 93CS56 Splash - 93CS46 Swift - 93CS66, 24C16 SX4 - 93CS66, 24C16 Vitara - 93CS46 Wagon-R - NEC78
Toyota	Auris - 93C86 Avensis - 93C56, 93C46, 93C66 Aygo - 93CS56 Camry - 93CS46 Cellica - 93CS46 Corolla - Sagem, VDO 93CS56, 93C86 Hiace - 93CS46 Hilux - 93CS66 HJ100 - 93CS56 IQ - 93CS66 Kijang - 93CS66 Landcruiser - 93CS46, 93CS56, 93CS66, 93CS86 Lexus - 93CS56 MR2 - 93CS46 Picnic - 93CS46 Prado - 93CS46 Previa - 93CS46 Prius - 93CS46, 93CS66, 93CS86

	Raum - 93CS46 Rav 4 - 93CS46, 93CS56 Sienna - 93CS46, 93CS66 Starlet - 93CS46 Yaris - 93CS46, 93CS56
Volvo	C30 - HCS12 S40 - 93CS56, HCS12 S60 - HC12, HCS12 S80 - HC08, HCS12, BOX V40 - 93CS56 V50 - HCS12 V70 - 93CS56, HC08, HC12, HCS12, Box XC60 - HCS12, BOX XC70 - HC12, HCS12 XC90 - HCS12
VW	Crafter - S95640 / EZS R270 Fox - Diag Golf 3 - VDO 35-3.9, TRW, Motometer, VDO Golf 4 - 24C0X / ECU 24C04 Golf 5 - 24CXX Eos - 24CXX Lupo - TRW Passat (B4) - Motometer, 93CS46, 93CS56 Passat (B6) - 24CXX Phaeton - 24CXX Polo (6N) - 24C02, TRW, Motometer T4 - MotoMeter up - Motometer HCS12
Wiesmann	Roadster - 24C02
Yes	Roadster & Cup/R - 93C86